

VALVE %
29.3

ECHO

CONTACT
0.00

RUN

AUTO CHGE

0 ABB% 100

AUTO LAYFLAT CAGE FINISHED DEV ALARMS ON

TARGET
65.50

ACTUAL
65.59

ERROR
0.09

GOTO HELP GOTO SETUP GOTO TRENDS GOTO BACK

PROCESS MONITOR 64

4095
STRENGTH
0

BUBBLE 1234 TARGET 1234 VALVE 1234

OUTLET 1234 INLET 1234

100
ABB%
0

GOTO BACK

CALIBRATE VALVE 103

MAX FLOW 1400

MAX PRESSURE 23

TUTOR

NEUTRAL 2400

TARGET PRESSURE 15

NEXT

VALVE 1400

RUN

PREV

0.0 100.0

Too Close!

VALVE CALIBRATION TUTOR
Press the NEXT Button to
Step through the process
of calibrating the
valve. EXTRUSION LINE
MUST BE STOPPED TO
COMPLETE THIS PROCEDURE.

GOTO BACK

SENSOR STATUS 62 GOTO BACK

ID#	STAT	ECHO	A	B	STRENGTH %	RANGE (INCHES)	TEMP OF
1.	✓		<input type="checkbox"/>		100	14.02	87
2.	✗	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	0	0.00	32
3.	✗	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	0	0.00	32
4.	✗	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	0	0.00	32
5.	✓				100	4.02	95
6.	✓		<input type="checkbox"/>		100	10.91	97
7.	✗	<input type="checkbox"/>	<input type="checkbox"/>		0	0.00	32
8.	✗	<input type="checkbox"/>	<input type="checkbox"/>		0	0.00	32
9.	✗	<input type="checkbox"/>	<input type="checkbox"/>		0	0.00	32